


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-140	Smoke	11/17/2008	ADS/TM	S11SS1016MH	Dry	Yes	1,412.58



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-140	Smoke	11/17/2008	ADS/TM	S11SS1016MH	Dry	Yes	1,412.58

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11SS1022G1	S11SS1022DE	S11SS1011MH	92.47571	8
S11SS1011G1	S11SS1011MH	S11SS1016MH	319.614	8
S11SS1016G1	S11SS1016MH	S11SS1008MH	225.0893	8
S11SS1006G1	S11SS1006MH	S11SS1008MH	226.9369	8
S11SS1001G1	S11SS1001MH	S11SS1006MH	227.9825	8
S11SS1023G1	S11SS1023DE	S11SS1001MH	124.2458	8
S11SS1008G1	S11SS1008MH	S11SS1013MH	69.71238	8
S11QQ1014G1	S11QQ1014MH	S11SS1008MH	126.5238	8

Observations & Photos

Obs_ID S1028-140-OB01

Address 2701 Spaulding Ave


Status Private

Source Cleanout

Location Yard - front

Nearest MH S11SS1001MH

Comments Smoke from cleanout in front yard. 2701 Spaulding Ave.



Picture \S1028-140-OB01-P01.jpg

Comments Front of house, 2701 Spaulding Ave.

Obs_ID S1028-140-OB02

Address 2722 Spaulding Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11SS1006MH

Comments Smoke from cleanout in front yard. 2722 Spaulding Ave.



Picture \S1028-140-OB02-P01.jpg

Comments Smoke indicated by flag on the right. Front of house, 2722 Spaulding Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-140	Smoke	11/17/2008	ADS/TM	S11SS1016MH	Dry	Yes	1,412.58

Obs_ID S1028-140-OB03

Address 2724 Spaulding Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11SS1006MH

Comments Smoke from cleanout in front yard. 2724 Spaulding Ave.



Picture \S1028-140-OB03-P01.jpg

Comments Smoke indicated by flag on the left. Front of house, 2724 Spaulding Ave.

Obs_ID S1028-140-OB04

Address 2728 Spaulding Ave


Status Private

Source Cleanout

Location Yard - front

Nearest MH S11SS1006MH

Comments Smoke from cleanout in front yard. 2728 Spaulding Ave.



Picture \S1028-140-OB04-P01.jpg

Comments Front of house, 2728 Spaulding Ave.

Obs_ID S1028-140-OB05

Address 5101 Pimlico Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11SS1016MH

Comments Smoke from cleanout in front yard. 5101 Pimlico Rd.



Picture \S1028-140-OB05-P01.jpg

Comments Front of house, 5101 Pimlico Rd.

Obs_ID S1028-140-OB06

Address 5103 Pimlico Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11SS1016MH

Comments Smoke from cleanout in front yard. 5103 Pimlico Rd.



Picture \S1028-140-OB06-P01.jpg

Comments Smoke indicated by middle flag. Front of house, 5103 Pimlico Rd.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-140	Smoke	11/17/2008	ADS/TM	S11SS1016MH	Dry	Yes	1,412.58

Obs_ID S1028-140-OB07

Address 5103 Pimlico Rd

Status Private

Source Service Lateral

Location Yard - front

Nearest MH S11SS1016MH

Comments Smoke from service lateral in front yard next to cleanout. 5103 Pimlico Rd.



Picture \S1028-140-OB07-P01.jpg

Comments Smoke indicated by flag on left. Front of house, 5103 Pimlico Rd.

Obs_ID S1028-140-OB08

Address 5103 Pimlico Rd

Status Private

Source Service Lateral

Location Yard - front

Nearest MH S11SS1016MH

Comments Smoke from service lateral in front yard under concrete next to cleanout. 5103 Pimlico Rd.



Picture \S1028-140-OB08-P01.jpg

Comments Smoke indicated by flag on right. Front of house, 5103 Pimlico Rd.

Obs_ID S1028-140-OB09

Address 5107 Pimlico Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11SS1016MH

Comments Smoke from cleanout in front yard. 5107 Pimlico Rd.



Picture \S1028-140-OB09-P01.jpg

Comments Front of house, 5107 Pimlico Rd.

Obs_ID S1028-140-OB10

Address 5109 Pimlico Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11SS1016MH

Comments Smoke from cleanout in front yard. 5109 Pimlico Rd.



Picture \S1028-140-OB10-P01.jpg

Comments Front of house, 5109 Pimlico Rd.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-140	Smoke	11/17/2008	ADS/TM	S11SS1016MH	Dry	Yes	1,412.58

Obs_ID S1028-140-OB11

Address 5111 Pimlico Rd

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11SS1016MH

Comments Smoke from cleanout in front yard. 5111 Pimlico Rd.



Picture \S1028-140-OB11-P01.jpg

Comments Front of house, 5111 Pimlico Rd.
